

120 BRUNSWICK ROAD, PORT ALBANY







HERITAGE AT ITS HEART

- Beautifully preserved 1900's brick home
- Terrific outlook to harbour, windfarm, port; walk to CBD
- Packed with fine original features
- · Modern kitchen, main bedroom, bathrooms
- 1009sqm block, garage, lovely gardens, solar power

4 1009 m2



Jeremy Stewart 0439 940 976 0898414022

jeremy@merrifield.com.au





120 BRUNSWICK ROAD, PORT ALBANY



Specification

Asking Price	Offers Above \$1,200,00	0 Land Size	1009.00 m2
Bedrooms	4	Frontage	See Certificate of Title
Bathrooms	2	Restrictive Covenants	See Certificate of Title
Toilets	2	Zoning	Residential / R30
Parking	1	School Zone	Albany Primary School & A.S.H.S
Sheds	1	Sewer	Yes
HWS	Gas	Water	Connected
Solar	Yes	Internet Connection	NBN Available
Council Rates	\$2,510.57	Building Construction	Brick & Iron
Water Rates	\$1,564.13	Insulation	Unknown
Strata Levies	N/A	Built/Builder	Approx 1903
Weekly Rent	N/A	BAL Assessment	N/A

-- Map Viewer Plus --




Author

Created: 18 flidtpan/loeag2024/stropr/uldampip/itenedp8teswa.gov.au/?address=120%20Brunswick%20Road%2C%20ALBANY%206330&theme¹15/95/id

0.007 0.014 0.02 0.027 km

120 Brunswick Rd, Albany WA 6330





This floor plan, description, dimensions and areas are provided as a guideline only and are approximate. Whilst care has been taken in the preparation of the information, buyers must inspect the property, make their own enquiries, take their own measurements or consult the architectural plans for exact dimensions. Neither the sellers nor the agent will be held responsible or liable for any discrepancies.



Author:

Created: 18 Notices Note and Note and Note of Note of

0.02 0.027 km

[©] Copyright, Western Australian Land Information Authority. No part of this document or any content appearing on it may be reproduced or published without the prior written permission of Landgate.

Disclaimer: The accuracy and completeness of the information on this document is not guaranteed and is supplied by Landgate 'as is' with no representation or warranty as to its reliability, accuracy, completeness, or fitness for purpose. Please refer to original documentation for all legal purposes.

WESTERN



TITLE NUMBER

Volume

Folio

1749 453

RECORD OF CERTIFICATE OF TITLE

UNDER THE TRANSFER OF LAND ACT 1893

The person described in the first schedule is the registered proprietor of an estate in fee simple in the land described below subject to the reservations, conditions and depth limit contained in the original grant (if a grant issued) and to the limitations, interests, encumbrances and notifications shown in the second schedule.



LAND DESCRIPTION:

LOT 200 ON DEPOSITED PLAN 300009

REGISTERED PROPRIETOR:

(FIRST SCHEDULE)

LINDA DOREEN HAYWARD MICHAEL WILLIAM PERRY BOTH OF 120 BRUNSWICK ROAD ALBANY WA 6330 AS JOINT TENANTS

(T P142680) REGISTERED 12/5/2022

LIMITATIONS, INTERESTS, ENCUMBRANCES AND NOTIFICATIONS:

(SECOND SCHEDULE)

Warning: A current search of the sketch of the land should be obtained where detail of position, dimensions or area of the lot is required.

Lot as described in the land description may be a lot or location.

-----END OF CERTIFICATE OF TITLE-----

STATEMENTS:

The statements set out below are not intended to be nor should they be relied on as substitutes for inspection of the land and the relevant documents or for local government, legal, surveying or other professional advice.

SKETCH OF LAND: 1749-453 (200/DP300009)

PREVIOUS TITLE: 1053-688

PROPERTY STREET ADDRESS: 120 BRUNSWICK RD, ALBANY.

LOCAL GOVERNMENT AUTHORITY: CITY OF ALBANY

NOTE 1: M018027 DEPOSITED PLAN 300009 HAS YET TO BE PRODUCED.



Transfer D386030

Volume 1053 Folio 688

WESTERN



AUSTRALIA



1749

453

CERTIFICATE OF TITLE

UNDER THE "TRANSFER OF LAND ACT, 1893" AS AMENDED

I certify that the person described in the First Schedule hereto is the registered proprietor of the undermentioned estate in the undermentioned land subject to the easements and encumbrances shown in the Second Schedule hereto.

Ŋ 뎐

Page 1 (of 2 pages) 1749

V0L.

Dated 19th December, 1986

REGISTRAR OF TITLES



ESTATE AND LAND REFERRED TO

and being lot 200 on DP 300009 Estate in fee simple in portion of Albany Town Lot 160, delineated on the map in the Third Schedule hereto.

FIRST SCHEDULE (continued overleaf)

Frederick Jack Bantock of 120 Brunswick Road, Albany, Retired Business Proprietor




SECOND SCHEDULE (continued overleaf)

NIL

REGISTRAR OF TITLES

THIRD SCHEDULE



The Deposited Plan for this Certificate of Title is yet to be produced. The Plan and Lot number have been allocated as an interim measure to enable issue of a Digital Certificate of Title. Please refer to this Title for the sketch of the land.

Land Parcel identifier amended Regulation 6 of Transfer of Land (Surveys) Regulations 1995 Corr. 1775-2000-01


9/9/04


NOTE: RULING THROUGH AND SEALING WITH THE OFFICE SEAL INDICATES THAT AN ENTRY NO LONGER HAS EFFECT ENTRIES NOT RULED THROUGH MAY BE AFFECTED BY SUBSEQUENT ENDORSEMENTS.



Superseded - Copy for Sketch Only

LT. 37 INITIAL K 2 INITIALS SEAL SEAL 15.05 11.19 12.49 REGISTERED OR LODGED IΜΕ 26.3.93 NOTE: RULING THROUGH AND SEALING WITH THE OFFICE SEAL INDICATES THAT AN ENTRY NO LONGER HAS EFFECT ENTRIES NOT RULED THROUGH MAY BE AFFECTED BY SUBSEQUENT ENDORSEMENTS. note: Ruling through and sealing with the Office seal indicates that an entry no longer has effect entries not ruled through may be affected by subsequent endorsements. REGISTERED 19.4.90 2**6.3.9**3 17.5.96 30.3.00 F146762 NUMBER E341870 F146763 6180315 H404900 INITIALS CANCELLATION Discharged INSTRUMENT Transfer Transfer Transfer Transfer See and the second SEAL as joint 53 TIME 9.02 4 Richard Alexander Eardly Milne and Hamish John Milne both of Post Office Box 18, Borden, REGISTERED John Homer and Shirley Ann Homer, both of 3 Carlisle Road, Kalamunda, as joint tenants. 19.4.90 9 CERTIFICATE OF TITLE VOL. 174 REGISTERED PROPRIETOR Sally Katherine Pierce Milne of 120 Brunswick Road, Albany. PARTICULARS Ltd. Robert Paton of 28 Saunders Street, Mosman Park. Bank Savings SECOND SCHEDULE (continued) FIRST SCHEDULE (continued) to Westpac E341871 Page 2 (of 2 pages) INSTRUMEN Mortgage tenants.





Plan Legend (summary) INFORMATION BROCHURE




This legend is provided to <u>Dial Before You Dig</u> users to assist with interpreting Water Corporation plans. A more detailed colour version can be downloaded from <u>www.watercorporation.com.au</u>. (Your business > Working near pipelines > Downloads)


WARNING - Plans may not show all pipes or associated equipment at a site, or their accurate location. Pothole by hand to verify asset location before using powered machinery.

WATER, SEWERAGE AND DRAINAGE PIPELINES CRITICAL PIPELINE (thick line) EXTRA CAUTION REQUIRED A risk assessment may be required if working near this pipe. Refer to your Dial Before You Dig information or call 131375. Pipes are not always labelled on plans as shown here – assume all pipes are significant and pothole to prove location and depth. **CANNING TRUNK MAIN** pressure main P.M. M.S. main sewer rising main (i.e. drainage pressure main) R 100AC GEYER PL P.M. AG47 Common material abbreviations: AC asbestos cement e.g. 100AC NOTE: AC is brittle and is easily damaged. cast iron CI 450RC 50 glass reinforced plastic **GRP** R· PVC - class follows pipe material (e.g.100P-12) 147.8 RC reinforced concrete steel S VC vitrified clay NON-STANDARD ALIGNMENT Pipes are not always located on standard alignments due to local conditions. (i.e. Other (3.0)than 2.1 m for reticulation mains and 4.5 m for distribution mains.) OTHER PIPE SYMBOLS MWA12345 or PWD12345 or CK43 Other numbers or codes shown on pipes are not physical attributes. These are Water Corporation use only. **CONCRETE ENCASEMENT, SLEEVING AND TUNNELS CONC ENC** May be in different forms: steel, poured concrete, box sections, slabs. 100S SL 150P 150AC 5.0 20. 225SU **CHANGE INDICATOR ARROW** Indicates a change in pipe type or size. e.g. 150mm diameter PVC to 150mm diameter asbestos cement (AC). 150AC 150AC **PIPE OVERPASS** The overpass symbol indicates the shallower of the two pipes. **VALVES** 150DAV 250PRV Many different valve types are in use. Valve may be in a pit or have a visible valve cover. There may be no surface indication. Valves may be shallower than the main or offset from it. e.g. A scour valve (SC) may 100SC have a pipe coming away from main pipeline on the opposite side to that indicated on the plan.



Printed on environmentally friendly paper








Date: 14/11/24 (valid for 30 days)

Seq # 247474149 Job # 38059351 BYDA Location: 120 Brunswick Rd Albany 6330

Scale: 1:800









SYMBOLS SHEET **GAS UTILITY NETWORK**


EXISTING GAS NETWORK Transmission Pipelines Distribution Pipelines

 Distribution Pipe MAOP 350kPa Distribution Pipe MAOP 70kPa


Distribution Pipe MAOP 7kPa

--- Not Gassed (none) Service Pipe

PROPOSED GAS ASSETS




ABANDONED GAS NETWORK



Abandoned Fitting SOLD Abandoned Valve SOLD

Abandoned Gas Main SOLD

COMPOUNDS



Pressure Reducing Station

L.P.G. Tank Hydrogen Plant

VALVES

* Isolation Valves Service Valves

MONITORING DEVICES

Flow Monitoring Device **Pressure Monitoring Device**

ASSOCIATED INFRASTRUCTURE

Associated Asset

DUCTS AND SLEEVES

Duct Horizontal Boring Sleeve = Road Crossing

Concrete Slabbing

FEATURES

REGULATOR SETS

Regulator Set

Boundary Regulator

DELIVERY POINTS

Δ

Meter

Interval Meter

Meter Set

PIPE JUNCTIONS

End Cap

Expansion Joint

Reducer

Tee

-0-Transition

Weld

Monolithic Joint

 \otimes Stopple Odorizer

Junctions

PROTECTION DEVICES

Test Point \Box

(A)Anode

(R)Rectifier

Side Elevation Linked Document Obstacle **PLS Pre-Laid Service** See Details **PLSS Pre-Laid Service Stairs** Not Connected Pre-Laid Service Tee **PLST Gas Service** BL Asset end on Main

Asset ends on Direction Peg

Gas Pit DOC 1.2m → Arrow Pointer **Proving Location**

Reference Line

Pressure Upgrade

Suburb

Local Government

Not Gassed

Asset Identifaction Legend

Offline Service

Critical Asset (See Cover Sheet WARNINGS)
Pipe Diameter (millimetres)

CoD

2. 3. Pipe Material:

Sign

SC

₩

NC

0LS

PE = Polyethylene, GI = Galvanised Iron, Cl = Cast Iron PVC = PVC, ST = Steel Alignment (in metres from property line)

4.

Pressure in main & Gas Type
5a) MAOP (Maximum Allowable Operating Pressure) 5b) Gas Type:

NG = Natural Gas.

H2B = Natural Gas Blended with % Hydrogen.

LPG = Liquefied Petroleum Gas.

Off-line Service service may not be straight line to meter. (WARNING OLS may not always be shown on plan). 6. See Cover Sheet for More Informattion.

Service Valve in the vicinity (NOTE: Service Valve may be "BURIED") 7.

8. Pre-laid Service laid in Common Trench


9. Main Status: (See Cover Sheet WARNINGS) 9a. AB & ABS = Abandoned Mains, Ab Sold. 9b. PROP = Proposed Mains

10. Customer Connection: Does not indicate actual location of Meter Position D2 (D = Domestic & 2 = Number of Meters)

C1 (C = Commercial & 1 = Number of Meters) 11. Additional detail available and Must be obtained **if within area of proposed works see Cover Sheet.** Depth of Cover (DOC) in metres.

12.







Report Damage: https://service.telstra.com.au/customer/general/forms/report-damage-to-telstra-equipments/

Ph - 13 22 03

Email - Telstra.Plans@team.telstra.com

Planned Services - ph 1800 653 935 (AEST bus hrs only) General Enquiries

TELSTRA LIMITED A.C.N. 086 174 781

Generated On 14/11/2024 14:40:35

Sequence Number: 247474146

CAUTION: Fibre optic and/ or major network present in plot area. Please read the Duty of Care and contact Telstra Plan Services should you require any assistance.

The above plan must be viewed in conjunction with the Mains Cable Plan on the following page

WARNING

Telstra plans and location information conform to Quality Level "D" of the Australian Standard AS 5488-Classification of Subsurface Utility Information.

As such, Telstra supplied location information is indicative only. Spatial accuracy is not applicable to Quality Level D.


Refer to AS 5488 for further details. The exact position of Telstra assets can only be validated by physically exposing it.

Telstra does not warrant or hold out that its plans are accurate and accepts no responsibility for any inaccuracy.

Further on site investigation is required to validate the exact location of Telstra plant prior to commencing construction work.

A Certified Locating Organisation is an essential part of the process to validate the exact location of Telstra assets and to ensure the asset is protected during construction works.

See the Steps- Telstra Duty of Care that was provided in the email response.



WARNING

Telstra plans and location information conform to Quality Level "D" of the Australian Standard AS 5488-Classification of Subsurface Utility Information.

As such, Telstra supplied location information is indicative only. Spatial accuracy is not applicable to Quality Level D.

Refer to AS 5488 for further details. The exact position of Telstra assets can only be validated by physically exposing it.

Telstra does not warrant or hold out that its plans are accurate and accepts no responsibility for any inaccuracy.

Further on site investigation is required to validate the exact location of Telstra plant prior to commencing construction work.

A Certified Locating Organisation is an essential part of the process to validate the exact location of Telstra assets and to ensure the asset is protected during construction works.

See the Steps-Telstra Duty of Care that was provided in the email response.



LEGEND Cable Jointing Pit Exchange (number / Letter indicating Pit Type) (Major Cable Present) Footway Access Chamber Elevated Joint (above ground joint on buried cable) (can vary from 1-lid to 12-lid) Pillar / Cabinet Telstra Plant in shared Utility trench (above ground / free standing) Aerial Cable Above ground complex equipment housing (eg RIM) Please Note: This equipment is powered by 240V Electricity Aerial Cable (attached to joint Use Pole eg. Power) oc Other Carrier Telecommunications Cable/Asset Direct Buried Cable Distribution cables in Main Cable ducts Dist Marker Post Installed Main Cable ducts on a Distribution plan MC Blocked or damaged duct. Buried Transponder Roadside / Front Boundary 2 pair lead-in to property from pit in street 1 Marker Post, Transponder pair working (pair ID 059) 059 Optical Fibre cable direct buried 1 pair dead (i.e. spare, not connected) Side / Rear Property Boundary Property Number Some examples of conduit type and size: Single to multiple round conduit Configurations 1.2.4.9 respectively A - Asbestos cement, P - PVC / Plastic, C - Concrete, GI - Galanised iron, E - Earthenware (attached text denotes conduit type and size) Conduit sizes nominally range from 20mm to 100mm P50 50mm PVC conduit Multiple square conduit P100 100mm PVC conduit Configurations 2, 4, 6 respectively A100 100mm asbestos cement conduit (attached text denotes conduit type and size) Some Examples of how to read Telstra Plans One 50mm PVC conduit (P50) containing a 50-pair and a 10-pair -50 cable between two 6-pits. approximately 20.0m apart, with a direct buried 30-pair cable along the same route 20.0 P50 AA - (cable information) Two separate conduit runs between two footway access AB - (cable information) chambers (manholes) approximately 245m apart A nest of four BA - (cable information) 100mm PVC conduits (P100) containing assorted cables in three P100 ducts (one being empty) and one empty 100mm concrete duct (C100) along 245.0

Protect our Network:

by maintaining the following distances from our assets:

- 1.0m Mechanical Excavators, Farm Ploughing, Tree Removal
- 500mmVibrating Plate or Wacker Packer Compactor
- 600mm Heavy Vehicle Traffic (over 3 tonnes) not to be driven across Telstra ducts or plant.
- 1.0mJackhammers/Pneumatic Breakers
- 2.0m Boring Equipment (in-line, horizontal and vertical)

For more info contact a <u>CERTLOC Certified Locating Organisation (CLO)</u> or Telstra Location Intelligence Team 1800 653 935

To: Stephanie Del Borrello


Phone: Not Supplied Fax: Not Supplied

Email: stephanie@merrifield.com.au

Dial before you dig Job #:	38059351	BEFORE
Sequence #	247474145	YOU DIG
Issue Date:	14/11/2024	Zero Damage - Zero Harm
Location:	120 Brunswick Rd , Albany , WA , 6330	

Indicative Plans	5			
		1		

-+-	LEGEND nbn (i)		
34	Parcel and the location		
3	Pit with size "5"		
(2E)	Power Pit with size "2E". Valid PIT Size: e.g. 2E, 5E, 6E, 8E, 9E, E, null.		
	Manhole		
\otimes	Pillar		
PO - T- 25.0m P40 - 20.0m	Cable count of trench is 2. One "Other size" PVC conduit (PO) owned by Telstra (-T-), between pits of sizes, "5" and "9" are 25.0m apart. One 40mm PVC conduit (P40) owned by NBN, between pits of sizes, "5" and "9" are 20.0m apart.		
-3 10.0m 9-	2 Direct buried cables between pits of sizes ,"5" and "9" are 10.0m apart.		
- 9 - 9-	Trench containing any INSERVICE/CONSTRUCTED (Copper/RF/Fibre) cables.		
- 9 9	Trench containing only DESIGNED/PLANNED (Copper/RF/Fibre/Power) cables.		
- 9 9-	Trench containing any INSERVICE/CONSTRUCTED (Power) cables.		
BROADWAY ST	Road and the street name "Broadway ST"		
Scale	0 20 40 60 Meters 1:2000 1 cm equals 20 m		



Emergency Contacts

You must immediately report any damage to the ${\bf nbn}^{\,{\rm m}}$ network that you are/become aware of. Notification may be by telephone - 1800 626 329.

-+-	LEGEND nbn (i)		
34	Parcel and the location		
3	Pit with size "5"		
(2E)	Power Pit with size "2E". Valid PIT Size: e.g. 2E, 5E, 6E, 8E, 9E, E, null.		
	Manhole		
\otimes	Pillar		
PO - T- 25.0m P40 - 20.0m	Cable count of trench is 2. One "Other size" PVC conduit (PO) owned by Telstra (-T-), between pits of sizes, "5" and "9" are 25.0m apart. One 40mm PVC conduit (P40) owned by NBN, between pits of sizes, "5" and "9" are 20.0m apart.		
-3 10.0m 9-	2 Direct buried cables between pits of sizes ,"5" and "9" are 10.0m apart.		
- 9 - 9-	Trench containing any INSERVICE/CONSTRUCTED (Copper/RF/Fibre) cables.		
- 9 9	Trench containing only DESIGNED/PLANNED (Copper/RF/Fibre/Power) cables.		
- 9 9-	Trench containing any INSERVICE/CONSTRUCTED (Power) cables.		
BROADWAY ST	Road and the street name "Broadway ST"		
Scale	0 20 40 60 Meters 1:2000 1 cm equals 20 m		



Emergency Contacts

You must immediately report any damage to the ${\bf nbn}^{\,{\rm m}}$ network that you are/become aware of. Notification may be by telephone - 1800 626 329.

ililoa braige of hear of Coast

Nor 160 - No 120 BRUNSWICK ROAD South Glaseow

NAMED "LAWLEY HOUSE" By the Present owners Sale Particulars 1995.

Deeds to 31st December 1883.

Brief description and history of its early residents.

Recently acquired photographs show the original face brick, confirming the stucco was added at a later date.

The timber valance, still in place, was originally across the whole verandah. Almost all other features remain intact including some original glass in the bay window, some red glass in the internal hall door has been identified as French Flash glass made only between 1880-1890.

Unsympathetic extensions to the rear were removed and replace by the present owners, with one more in keeping with the age and character of the home.

HISTORY

The land formed part of the original layout of the town of Albany 1831. It was largely on these blocks from Parade Street to the present Lawley Park that the town of Albany grew in the early years (see map - site of Albany 1836).

In 1836 new government buildings were established on what is now Lawley Park. A road from the front of the property linked it to the gaol at the top of the hill and the army garrison at the foot.

Thomas Wilkinson Howe - expiree arrived per ship "Dudbrook" on 10th December 1853 and 30 years later (December 1883) applied to become registered owner of the property. He became sole proprietor on the 21st December 1883.

In 1885 aged 33 he married Catherine Baker then 13 years. Catherine, her Mother and Father Robert Baker had arrived in the colony per ship "Scindian" on 1st June 1850. The "Scindian" carried 200 passengers and the first 75 convicts to the colony.

Within three months of becoming proprietor on the 15th March 1884 the certificate was partially cancelled, the "southern moiety" being transferred to John Robinson - Merchant.

J. Robinson transferred to Albany as manager of the National Bank in 1878. In 1883 he resigned to take partnership in McMail and Co general merchants. On the 15th March 1884 he became proprietor of Lot 60. It is believed he designed the house. In 1887 he liquidated McMail and Co to form the Partnership of Drew Robinson and Co. The company expanded rapidly and in 1891 moved into the new building which ran from Stirling Terrace to Frederick Street (now Stirlings). That year on 24th October 1891 the property was sold to Solicitors Edward George Sydney Hare and Samuel Johnson Haynes.

Samuel Same Same

In 1889 having bought the practice of Hare Samuel Johnson Haynes had been joined by John Robinsom's son R.T. Robinson forming the practice of Haynes Robinson. Late in 1893 plans were drafted for the new office building in lower York Street. He mortgaged the Brunswick Road property to Horace Edgerton-Warburton and Emily Martha Rosina Edgerton-Warburton "along with other lands". On the 5th February 1894 for the sum of £500. In April of that year the new offices were completed. The connection to the Robinsons continued when the Brunswick Road property was transferred to Annie Challend (married woman "for her sole and separate use"), 21st February 1903.

A. Challend was a member of the literary society and devout Methodist, she attended the funeral of Mrs J. Robinson on 2nd February 1910, she auctioned her furniture from the house on 9th June 1920 before she died in 1924 and Letters of Administration were granted to her son Walter Louis Challend, Ironmonger. Walter received presentations from Drew Robinson and staff for his wedding and on his resignation in 1910. Although the property remained in his name it is known members of the Norman family lived in the house in 1920/22.

On the 21st April 1937 the property was transferred to Sydney Wentworth Clapp, Farmer and his wife Hanna also devout Methodists. It became a venue for musical soirces and choral society events. They stayed 23 years until their deaths in February and March 1959.

Lawley House

AUTHOR City of Albany

PLACE NUMBER 15440



LOCATION

120 Brunswick Rd Albany

LOCATION DETAILS

OTHER NAME(S)

Ailsa Craige

LOCAL GOVERNMENT Albany REGION Great Southern

CONSTRUCTION DATE

Constructed from 1903

DEMOLITION YEAR N/A

Statutory Heritage Listings

ТҮРЕ	STATUS	DATE	DOCUMENTS
Heritage List	Adopted	27 Oct 2020	

Heritage Council Decisions and Deliberations

TYPE	STATUS	DATE	DOCUMENTS
(no listings)			

Other Heritage Listings and Surveys

ТҮРЕ	STATUS	DATE	GRADING/MANAGEMENT CATEGORY
Municipal Inventory	Adopted	30 Jun 2001	Category B
Local Heritage Survey	Adopted	27 Oct 2020	Considerable

Statement of Significance

Lawley House has cultural heritage significance for the following reasons: The place reflects the typical dwelling of a rising middle class that emerged from the commercial and service industries that developed around the port of Albany in the latter part of the 19th century particularly when Albany was the main port for Western Australia. The place is one of a group of significant residences built during the Late Victorian/Federation period along this eastern end of Stirling Terrace, just outside of the Stirling Terrace Heritage Precinct, many of which were used as boarding and guest houses given their proximity to the town centre, railway station and harbour owing to Albany's growing popularity as a summer holiday resort. The place is associated with Francis Bird, well-known and prominent WA architect, including serving as Chief Government Architect for WA, who then started his own private practice after moving to Albany where he lived with his family for many years at the Strawberry Hill Farm

and designed many significant residential buildings. The place is associated with William E Mawson well-known local building contractor and one-time Mayor of Albany. The place is one of many associated with sea trade and port affairs in Brunswick Road and the eastern end of Stirling Terrace.

Physical Description

Some of the notable features of this place include: • Prominent location - high streetscape value • High authenticity - few modifications • Stone foundations • Cement steps lead up to front entrance • Rendered brick facade • Prominent projecting wing • Gable over projecting bay window with three panels • Decorative timber barge board and finial on gable • Distinctive coloured glass incorporated in building (owner information) • Verandah under separate roof across part of front elevation • Decorative timber balustrading and fringe on verandah • Two chimneys with moulded capping Some obvious modifications include: • Rear extensions

History

Thomas Wilkinson Howe, who arrived in Australia on the ship 'Dudbrook' in 1853, originally owned the land on which this house was built. He became sole proprietor of the property in 1883. The following year, part of the title was transferred to John Robinson, who was a prominent Albany businessman at that time. In 1891 he sold Lot 160 to Samuel Haynes, a prominent Albany lawyer, who held it until 1903. The next owner was Annie Challend, who commissioned Francis Bird and William Mawson to build her a residence in 1903. The building was designed by Francis Bird, who served as Chief Government Architect for WA in 1883. By 1889, Bird and his family had settled in Albany and lived at/owned the historic Strawberry Hill Farm. In Albany, Bird worked as a private architect and also designed other significant residences including 23 Aberdeen Street (which became the Albany Club), 55 Burt Street (The Priory), 64 Spencer Street and 136 Brunswick Rd (Parkville). William E Mawson, originally from England, first went to Beverley where we served as a Methodist Minister before settling in Albany where he established himself as a carpenter, builder, painter and paperhanger. He was active in local government, being Chairman of the Albany Road Board and serving as Mayor for one term in 1911. He was also instrumental in having the Government Water Scheme established in Albany. He died 23 May 1947 at his home in Napier aged 80. Mawson also built the Burvill's home Burleigh in Elleker. Annie Challend lived at Lawley House until 1920 and after Annie's death in 1924 her son Walter became the new proprietor until 1937. Available records show that the Clapp family owned the property until 1959. It is thought that this residence was considered an 'establishment' house, i.e. part of the banking-maritime-cultural circle. Research indicates that it was used as a venue for musical soirees and choral society events. An early photograph of the house, from the collection of W. E. Mawson, Master Builder, shows it was originally face brick, with the stucco being added at a later date. The timber valance was once across the whole verandah. Almost all other features remain intact, including some original glass in the bay windows. Some red glass in the internal hall door has been identified as French flash glass made only between 1880 and 1890. Unsympathetic extensions to the rear were replaced by the present owners in 1994-95 with additions more in keeping with the character of the home. In c2012, the owner received a small grant from the City of Albany to reinstate missing sections of the decorative timber valance to the front verandah.

Integrity/Authenticity

Integrity: High Authenticity: High/Moderate

Condition

Good

Associations

NAME	TYPE	YEAR FROM	YEAR TO
Francis Bird	Architect	-	-

References

REF ID NO	REF NAME	REF SOURCE	REF DATE
	Heritage Database	City of Albany	1995
	L Johnson; "Town of Albany Heritage Survey".		1994
	Heritage TODAY Site visit and Assessment		1999

Creation Date 10 Mar 2000

Last Update 18 Nov **Publish place record online (inHerit):** Approved 2021

Disclaimer

This information is provided voluntarily as a public service. The information provided is made available in good faith and is derived from sources believed to be reliable and accurate. However, the information is provided solely on the basis that readers will be responsible for making their own assessment of the matters discussed herein and are advised to verify all relevant representations, statements and information.

×

Category B

Requires a high level of protection.
 Provide maximum encouragement to the owner under the City of Albany Town Planning Scheme to conserve the significance of the place.
 A more detailed Heritage Assessment/Impact Statement to be undertaken before approval given for any major redevelopment.
 Incentives to promote heritage conservation should be considered.

Considerable

Very important to the heritage of the locality.



258 York Street P0 Box 5001 Albany WA 6332 08 9841 4022 admin@merrifield.com.au www.merrifield.com.au

ESTABLISHED IN ALBANY FOR OVER 80 YEARS

03/12/2024

The Client
C/- Merrifield Real Estate
258 York Street
ALBANY WA 6330

To whom it may concern,

RE: RENTAL APPRAISAL - 120 BRUNSWICK ROAD, PORT ALBANY

We wish to thank you for the opportunity to provide a rental appraisal for the above-mentioned property.

After viewing the property and taking into consideration its location and condition, we feel we can expect to achieve circa \$750.00 - \$800.00 per week in the current rental market.

In accordance with requirements to minimum security, internal blind cords and RCD and Smoke Alarm checks, please make your own investigations as to whether this property is compliant. Information can be obtained through the below websites:

Smoke Alarm guidelines:

DFES_fireinthehome-smokealarm-renting-selling-FAQs.pdf

Internal Blind cord requirements:

Obligations of landlords - corded internal window coverings | Department of Mines, Industry Regulation and Safety (commerce.wa.gov.au)



Minimum Security Requirements:

Rental property security standards | Department of Mines, Industry Regulation and Safety (commerce.wa.gov.au)

Should you have any questions, please feel free to contact me on (08) 9841 4022.

Yours faithfully,

Lisa Dunham

Senior Property Manager

Please note, as per our Professional Indemnity Policy, we must state the following: The Statements have been prepared solely for the information of the client and not for any third party. Although every care has been taken in arriving at the figure, we stress that it is an opinion only and not to be taken as a sworn valuation. We must add the warning that we shall not be responsible should the Statements or any part thereof be incorrect or incomplete in any way. This appraisal is deemed valid for 30 days from the date completed, or such earlier date if you become aware of any factors that have any effect on the property value.